




State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

June 14, 1999

TO: Minerals File
FROM: Lynn Kunzler, Reclamation Specialist 
RE: Site Inspection, American Stone Company, Rosebud Quarry, S/003/026, Box Elder County, Utah

Date of Inspection: June 10, 1999
Time of Inspection: 11:30 a.m.
Conditions: Clear
Participants: Lon Thomas, Operator; Donald Johnston, Johnston Engineering and Surveying; Lynn Kunzler and Doug Jensen, DOGM

Purpose of Inspection: Survey current disturbed areas.

As per the Division's May 27, 1999 letter to Mr. Lon Thomas, The Division was notified on June 8, 1999 of a scheduled survey to be conducted on June 10, 1999. The purpose of this survey is to determine the acreage that has been disturbed by mining operations at the Rosebud Quarry.

The entire disturbed area was surveyed using Trimble GPS surveying equipment. Division personnel verified the location for each data point of the survey and each point was marked with survey flagging. The survey was conducted in two segments, each encompassing one of the two quarry pits. The first area included the green stone pit, storage areas, fuel area. Field calculations resulted in 3.64 acres of disturbance. The second area included the white stone quarry, storage areas and access from existing public access roads. Field calculations resulted in 2.61 acres of disturbance. The total disturbed area is 6.25 acres (this includes a 12-foot road through the lower area of approximately 0.1 miles long or less than 0.2 acres).

Mr. Johnston indicated that they would complete the survey and submit the final version to Mr. Thomas next week. Mr. Thomas was instructed to call the Division when he received the survey to schedule a meeting (if he desired) to discuss possible options, time frames etc. that may be available to him vs. the Division issuing a formal Notice of Non-Compliance.

Also noted during this site visit, there was no activity at the site. All equipment has been moved from the site as well as the palletted stone that was observed during the last inspection. Also, the fuel tank has been removed and the contaminated soil from fuel leakage/spills has been cleaned up. A small camp trailer was the only facility remaining on site.

Several photos were taken to document site conditions.

cc: Mike Ford, BLM
S03_26.ins